
F16, 1


F16.2 Compress quantity of MgBz powder Sinter the quantity of Mg Bz powder while being compressed T24 Cool the sintered body

H 1 0 0

Manager 1

0.00





F16.5

Provide sold pellet of MgBz Direct beam of pulsed laser onto the pellet to eject particles of MgBz

7 (0.00)

